


Astro-Optics Division



Moderate resolution reprint of: "UV-Nikkor 105mm f/4.5 Instruction Manual"

Scanned from original in Company Seven's Archives. Lens technical data applies to current limited production model Nikon UV-105mm lenses sold by Company Seven.

Used explicitly by permission granted to Company Seven, not to be reproduced or circulated without permission.

14300 Cherry Lane Court Laurel, Maryland 20707 301-953-2000 Correspondence: Box 2587 Montpelier, Maryland 20709-2587 info@company7.com



No reproduction in any form of this booklet, in whole or in part (except for brief quotation in critical articles or reviews), may be made without written authorization from Nippon Kogaku K.K.

NIPPON KOGAKU K.K.

Fuji Bldg., 2-3, Marunouchi 3-chome, Chiyoda-ku, Tokyo 100, Japan Phone: 81-3-214-5311 Telex: J22601 (NIKON) Fax: 81-3-201-5856

Printed in Japan 8&015-B07

UV-Nikkor 105mm f/4.5

Nikon

使用説明書 INSTRUCTION MANUAL



各部の名称4
はじめに5
紫外線撮影の方法6~10
光源6
フィルター6 - 7
感光材料8
ピント合わせ······· 9
露出
拡大撮影
倍率を決めてから撮影するとき
被写界深度
露出の決め方一可視光線撮影時12~13
TTL露出計付きカメラボディの場合
TTL露出計付きでない場合!
赤外線撮影について
ファインダースクリーン
レンズ取扱上の注意
性能
被写界深度表3
接写表3
付属フィルターの分光透過曲線図38

CONTENTS—	_	_	_	
NOMENCLATURE				18
BEFORE USING THE LENS				19
UV PHOTOGRAPHY				
Light Source				20
Filter				20~21
Photosensitive Materials				22
Focusing				
Focusing on predetermined				
reproduction ratio				24
Depth of field				
Exposure				25
UV photography at high magnification	on			25
DETERMINING EXPOSURE IN				
VISIBLE LIGHT		+		26~27
With built-in TTL metering		,	,	26
Without TTL metering				27
INFRARED PHOTOGRAPHY				28
RECOMMENDED FOCUSING SCREE				
LENS CARE				
SPECIFICATIONS				31
DEPTH-OF-FIELD TABLES				
CLOSE-UP TABLES				34~35

はじめに-

を行ってください。

このたびはニッコールレンズをお買い上げいただきありが とうございました。

このレンズは6群6枚で構成され、200nmより長い波長を 透過するため、紫外線領域の撮影に有効です。紫外線撮影 を行うには、可視光線や赤外光線を除去するために光源ま たはレンズに紫外線透過フィルターを装着する必要があり ます。付属のフィルターホルダーAF-1, UR-2リング、紫外 線透過フィルターを使用すると便利です。付属の紫外線透 過フィルターは330nm 付近に透過中心波長があり、220~ 420nm の波長の光を透過します。また可視光でピントを合 わせれば紫外線撮影時にピント補正する必要はありません。 通常の一般的なカラー撮影を行う場合にはL37CまたはL39 フィルターを装着して使用してください。 このレンズは紫外線を充分に透過させるため一部に発石を 使用していますが、螢石の熱的特性のため温度変化による

ピントずれを発生します。撮影に際してはピントの再確認

コーティングは紫外線領域でのレンズの表面反射を滅じる 特殊なコーティングが施してあり、波長 220nm-900nmの 全域で約70%の透過率です。また $\infty-1/2$ 倍まで各波長に わたって収差の変動が少なく、ディストーションもほとん どありません。



各部の名称 -

- 1. 被写界深度目盛
- 2. 絞り目盛
- 3.露出計連動爪
- 4. 露出計連動ガイド
- 5.ファインダー内表示用絞り目盛
- 6. 赤外マーク
- 7. 開放F値連動ガイド
- 8. EE 連動ガイド
- 9. 絞りリング
- 10. 着脱リング
- 11. クランブ
- 12. UR-2リング
- 13. 紫外線透過フィルター
- 14. 距離指標/絞り指標
- 15. 距離目盛
- 16. 倍率目盛
- 17. 距離リング
- ゼラチンフィルターホルダーAF-I(UVニッコールI05mmF4.5Sレンズでは紫外線 透過フィルターのホルダーとして使用します)

紫外線撮影の方法-

光源

光源中に紫外線が多量に含まれていることが必要です。しかし紫外線は人体に有害ですから、紫外線光源を長時間使用したり直視することは避け、保護眼鏡を着用する必要があります。紫外線写真に利用できる光源には、次のものがあります。

- (1) 太陽光
- (2) ブラックライト蛍光灯
- (3) 水銀ランブ
- (4) キセノンランブ
- (5) 特種ストロボ、フラッシュバルブ
- (6) その他

フィルター

紫外線撮影を行うためには可視光や赤外光を除去するため に、光源またはレンズに紫外線透過フィルターを装着する 必要があります。

UVニッコール105mmF4.5Sには、紫外線透過フィルターが付 属品として用意されています。紫外線透過フィルターの装 着は次の手順で行います。

- 1.付属のUR-2 リングを反時計方向へ回して開きます。
- 2. 紫外線透過フィルターを2つのリングの間にはさみ、 UR-2を時計方向へ回して閉じます。
- フィルターをはさみ込んだUR-2を、フィルターホルダー AF-1 に時計方向へねじ込んで止まるまで回して取り付けます。
- 4.AF-I をレンズ先端に取り付けます。このとき、カチッと いうまでAF-I を時計方向に回します。

なお、付属の紫外線透過フィルターの透過率特性につきましては、P.36の図をご覧ください。







感光材料

銀塩フィルムは乳剤層内のゼラチン中にハロゲン化銀粒子を分散させ、これを感光膜層としています。ハロゲン化銀自身は200nm付近にまで感光能力がありますが、これを包んでいるゼラチンは300nm以下の紫外線を吸収するので、一般のフィルムは300nm以下の紫外線撮影には適しません。紫外線写真に利用できるフィルムは以下の通りです。

(1) 長波長紫外線写真用フィルム

一般のパンクロ、レギュラー感材で十分撮影できます。例:トライ・X、テクニカルパン2415、ネオパンSS、ミニコビーなど

(2) 短波長紫外線写真用フィルム

専用フィルムが必要となります。

例: コダック スペクトロスコッピック タイプIO3-O 同じく タイプIO3-F、赤外フィルムなど

(3) カラーフィルム

通常のカラーフィルムを使用することにより、紫外線写真 の撮影が可能です。この場合、得られる写真は青色のモノ クローム画像となります。 なお、赤外フィルムを紫外線写真用に利用する場合は、使用するフィルターの分光特性を十分検討する必要があります。紫外線透過フィルターのなかには、約650nm以上の赤一赤外光も透過させるタイプのものがありますが、この組み合わせでは、フィルム上に紫外光のみならず、不必要な波長による画像(情報)が重なる可能性があります。

ピント合わせ

ビント合わせの際は、フィルターホルダーの上端の止め具 を回してホルダーを開き、可視光でビントを合わせます。 ビント合わせが終わりましたら、ホルダーを閉じ、止め具 を固定してフィルターでの撮影を行います。

距離リングにはクランブが付いています。ピント合わせを 行った後、締めつけておくと不用意に距離リングがズレた りしませんので便利です。ただし、クランブが締めつけら れても距離リングは完全には固定されません。

無理な力を加えて回転させることはお避けください。





露出

紫外線写真では、一般にカメラの露出計などを使用するこ 別売 とができません。フィルムの紫外線感度や、光源の分光エ の紫 ネルギー分布、フィルターの分光透過率、被写体の紫外線 テレ 反射率等を考慮した上で、試し撮りを行う必要があります。 ん。 実写データの一例を次に示します。

例:人間の皮膚の紫外線写真を撮る場合

光 源	ブラックライト(BLB)40W×4本
フィルター	紫外線透過フィルター(付属)
フィルム	トライ-X(D-76、20度、7分)
3% 出	f/5.6で1/125秒前後

拡大撮影

別売りのPN-I1などの中間リングを装着すると I/2 倍 以上 の紫外線撮影も可能です。しかし、クローズアップレンズ、 テレコンバーターなどを装着して使用することはできませ ん。

倍率を決めてから撮影するとき---

距離目盛のすぐ上に、倍率目盛がオレンジ色で記してあります。この目盛により、先に倍率を決めてから撮影することもできます。たとえば、I:5の倍率で撮影したいとき、内側の目盛の5を距離指標(黒点)に合わせておき、カメラボディを前後してピントを合わせます。被写界深度表をご覧になれば、各倍率での撮影距離を簡単に求めることができます。なお、距離リングのクランプの位置が倍率I:4の位置になります。

被写界深度.

被写体の前後のどの範囲が鲜明に写るかという被写界深度 の範囲は、鏡筒の距離指標の両側の被写界深度目盛によっ て示されます。この目盛線は、絞りリングの絞り値と同じ 色で示されています。被写界深度は、この2本の線が示す 距離目盛で読むことができます。ただし、∞~Imの範囲 で使用してください。近距離ではズレが生じるため被写界 深度目盛は使用できませんので、カメラボディの絞り込み ボタンを押してファインダー内で深度を確認するか、被写 界深度寿失(P32)をご覧ください。



露出の決め方一可視光線撮影時一

TTL露出計付きカメラボディの場合

レンズのみで使う場合

AI方式カメラボディ、従来のTTL露出計付きカメラボディ、いずれの場合も開放測光で露出を決めます。

ただし、後者の場合には、開放F値のセットを忘れずに行ってください。

接写用アクセサリーを併用する場合

このレンズとカメラボディの間に接写用アクセサリーを取 りつけた場合の測光は右の表のようになります。

ただし、いずれの場合も、レンズを逆向きで使用する場合 は絞り込み測光となります。

カメラボディ	アクセサリー	测光方式	開 放 F 値 セットの操作
AI方式 カメラボディ	PN+II	開放測光	不要
AI方式 歩 カメラボディ	PN+I	絞り込み測光	
AI方式 カメラボディ	ベローズ アタッチメント	絞り込み消光	-
従来 カメラボディ	PN-11	絞り込み測光	-
従来 カメラボディ	PN-I	開放測光	要
従来 カメラボディ	ベローズ アタッチメント	絞り込み測光	-

東カメラボディによっては、PN-1が使用できないものもあります。

TTL露出計付きでない場合

レンズを繰り出し、撮影倍率を増大すると、像の明るさは 減少します。TTL露出計を使わない場合は、撮影倍率に応 じて露出の増加(露出倍数)を考慮する必要があります。 右の表は、撮影倍率1:10以上のときの露出倍数および絞

右の表は、撮影倍率 | : 10以上のときの露出倍数および絞 りを開く量を示します。

絞りを | 段以上開きたくない場合は、シャッタースピード も合わせて変えて補正することもできます。たとえば、撮 影倍率 | : 1.2のときは、シャッタースピードを | 段低速に して絞りを 3/4 段開くか、またはシャッタースピードを 2 段低速にして絞りを 1/4 段絞り込むかして、補正を行いま す。

撮影倍率	露出倍数	絞りを開く量
1:10	1.2	約 1/4 絞り
1:8	1.3	" 1/3 "
1:6	1.3	" 1/3 "
1:4	1.5	" 2/3 "
1:2	2.2	" 11/4 "
1:1.8	2.3	" 11/4 "
1:1.6	2.5	" 11/3 "
1:1,4	2.8	" 1½ "
1:1.2	3.2	" 1% "
1:1	3.8	" 2 "

1:2を超える撮影倍率は、PNリングを併用した場合に得られます。

赤外線撮影について-

赤外線で撮影を行う場合は、可視光とピント位置が多少ずれる場合があります。このため、レンズ着説リング上に赤外目盛指標(赤色の点)で修正量の目安(使用するフィルム等により多少異なる場合があります)を表示してあります。赤外線撮影の一般的手順は、まずファインダーでピントを合わせます。つぎにその撮影距離を赤外目盛まで移し、使用フィルターを着けて撮影します。



ファインダースクリーン---

ニコンF3シリーズカメラには21種類、ニコンF2シリーズ カメラには19種類のファインダースクリーンが用意されて います。

下表を参考の上、最適のファインダースクリーンをお選び ください。

スクリーンカメラ	A/L	В	С	D	E	GI	G2	G3	G4	н	H2	НЗ	H4	J	K/P	M	R	Т	U
F3	0	0		0	0			0	0			0	0	0	0		0	0	0
F2	0	0		0	0			Ö	Ö			0	0	0	0		0		

■テレコンバーターTC-14またはTC-14BSを装着した場合※

スクリーンカメラ	A/L	в	С	D	Ε	G1	G2	G3	G4	н	H2	НЗ	H4	J	K/P	M	R	Т	U
F3	۰	0		0	0									0	۰		۰	•	•
F2	•	0		0	0									0	۰		۰		

■テレコンバーターTC-300またはTC-301Sを装着した場合※

スクリーンカメラ	A/L	в	С	D	E	G1	G2	G3	G4	н	H2	НЗ	H4	J	K/P	M	R	Т	U
F3	•	0		0	0			0	0					0	۰		۰	•	•
F2	۰	0		0	0			0	0					0	٠		۰		

※テレコンバーターは紫外線撮影時は使用できません。

■構図の決定やピント合わせの目的には

: 好適です。

:スプリット、マイクロブリズムでは、ビント合わせが できません。

○:視野の一部が多少見にくくなりますが使用できます。

■:測光はできませんが、ピントは合わせられます。

空欄:使用不適当です。

F3、F2シリーズ以外のAIカメラボディをご使用の場合は、 上記表中F3欄の該当する組み合わせを参照してください。 また、K2、B2、E2スクリーンはそれぞれK、B、Eスクリ ーンの機をご覧ください。

レンズ取扱上の注意 -

- ●レンズの満掃は、むやみに拭かないで、ホコリを拭う程度にしてください。万一指紋や汗がついたときは、柔らかい清潔な木綿のふきんに無水アルコール(エタノール)を少量湿らせ、中心から外側へ渦巻状に、拭きムラ、拭き残りのないように注意しながら軽く拭きます。
- ●レンズをボディにつけたままで、ご使用にならないときは、必ずレンズキャップをしておいてください。
- ●レンズをケースに収納する場合は、必ず前後にレンズキャップをしておいてください。また、距離環は∞にして収納してください。レンズを繰り出したまま収納しますと、レンズに異常な圧力が加わったり、ケースが変形するおそれがあります。

焦 点 距 離 105mm

最大口径比 1:4.5

レンズ構成 6群6枚

画 角 23°20′

距 離 目 盛 ∞-0.48m、1.57ft(併記)

倍事目盛1:10~1:2

紋 り 目 盛 4.5-32 ファインダー内表示用絞り目 感併記

皎 り 方 式 自動絞り

測 光 方 式 開放測光

マ ウ ン ト ニコンドマウント


アタッチメントサイズ 52mm (P=0.75mm)

大きき約68.5mm(最大径)×108mm(バヨネット基準面から先端まで)、全長116.5mm

量 約515g

アクセサリー

付 属	別売り
52mm スプリング式前キ ャップ	52mm ねじ込み式フィル ター
裏ぶたLF-I	ハードケースCL-I5S
ゼラチンフィルターホル	ソフトケースNo.63
ダーAF-I	ブラスチックケースCP-9
UR-2リング	☑テレコンバーターTC-I4BS
52mm 角紫外線透過フィルター	図テレコンバーターTC・301S



NOMENCLATURE -

- Depth-of-field indicators
- 2. Aperture scale
- 3. Meter coupling shoe
- 4. Meter coupling ridge
- 5. Aperture-direct-readout scale
- 6. Infrared focusing index
- 7. Aperture indexing post
- 8. EE servo coupling post
- 9. Aperture ring
- 10. Mounting ring
- 11. Focusing ring screw
- 12. Filter holder ring UR-2
- 13. UV transmitting filter
- 14. Aperture/distance index
- 15. Distance scale
- 16. Reproduction ratio scale
- 17. Focusing ring
- Gelatine filter holder AF-1 (used as UV transmitting filter holder with this lens)

BEFORE USING THE LENS-

Thank you for your kind patronage of Nikon. Before using your new lens, read the following carefully so you get the most out of your lens now and for years to come.

The UV-Nikkor 105mm f/4.5 is specially designed for UV (ultraviolet) photography, and with virtually no variation in the focus position between visible rays and UV rays, it eliminates clumsy focus adjustments.

Special coating is applied to the air-to-glass surface of the lens element to reduce reflection under UV rays.

At all focused distances in every wavelength range, aberration is minimal and distortion is eliminated. Fluorspar is applied to some lens elements to ensure adequate transmission of UV rays.

Of course, ordinary photography can be performed in visible light.

UV PHOTOGRAPHY-

Light Source

A considerable amount of UV radiation is required. As UV rays can be harmful to the human body, however, avoid prolonged use of and direct viewing of UV light sources, and wear protective eyeglasses.

Light sources for UV photography are:

- 1. Sunlight
- 2. Fluorescent blacklights
- 3. Mercury lamps
- 4. Xenon lamps
- 5. Special strobes and flashbulbs
- 6. Others

Filter

Use the supplied UV transmitting filter to eliminate visible and infrared rays. The UV transmitting filter has a transmission band centered on 330nm, and transmits UV rays at wavelengths from 220 to 420nm. (See chart on page 36.)

Filter attachment procedure is:

- Unscrew the filter holder ring UR-2 to open the UR-2.
- Put the filter on the one ring and screw the rings together.
- 3. Screw the assembly into filter holder AF-1.
- Screw the AF-1 into the front of the lens until it clicks.

For ordinary color photography, use a 52mm screwin type L37C or L39 filter to eliminate UV rays.









Photosensitive Materials

Films which may be used in UV photography are:

- For long-wavelength UV photography
 General panchromatic and regular photosensitive materials are adequate: Tri-X, Technical Pan 2415, Neopan SS, Minicopy film, etc.
- For short-wavelength UV photography
 Special film is required: Kodak Spectroscopic type 103-O, type 103-F, infrared film*, etc.
 - * When using infrared film and a UV transmitting filter other than the one supplied, check the spectral characteristics of the filter in use. Some UV transmitting filters transmit light in the red and infrared regions at wavelengths of 650nm and longer, and may create overlapping images caused by unwanted wavelengths on the film.

3. Color Film

General color films can be used. The image will appear in a blue monochrome color.

Focusing

Focusing should be performed without a filter. Simply turn the filter holder knob to open the filter holder for focusing, and close it again for shooting.

To focus, first loosen the tightening screw on the focusing ring. To keep the focusing ring from moving, be sure to tighten the screw. The tightening screw makes it difficult to accidentally move the focusing ring, but does not lock it in place. Although it is possible to turn the focusing ring with the screw tightened, do not attempt it.

Thermal characteristics of fluorspar cause a focus shift when temperature changes; check the focus in the viewfinder before shooting.





Focusing on predetermined reproduction ratio

The reproduction ratio scale, inscribed in orange above the distance scale on the focusing ring, enables you to photograph at a predetermined ratio.

For example, to photograph at a reproduction ratio of 1:5, turn the focusing ring until the number "5" is aligned with the distance index, then aim at the subject and adjust your position (closer to, or farther away from the subject) until the image appears sharp on the focusing screen.

The focusing ring tightening screw represents position "4", for one-fourth.



Depth of field

the table on pages 32 and 33.

Depth of field can be checked with the color-coded depth-of-field indicators engraved on the lens barrel. The pairs of colored lines correspond to the f-numbers of the same color on the aperture scale. If your camera has a depth-of-field preview function, it is possible to check the depth of field in the viewfinder. (For details, see camera instruction manual). Depth of field can also be checked by referring to

Exposure

Camera exposure meters cannot be used in UV photography—test shootings are required. The UV sensitivity of the film, the spectral energy distribution of the light source, the spectral transmissivity of the filters, the UV reflection ratio of the subject, etc., should all be considered.

An example of photographic data to take UV photographs of human skin

Light source	Blacklight (BLB) 40W × 4
Filter	UV transmitting filter supplied
Film	Tri-X (D-76, 20°, 7 min.)
Exposure	Approx. 1/125 sec. at f/5.6

UV photography at high magnification

With the optional PN ring, UV photographs at greater than 1:2 reproduction ratio are possible. However, close-up attachment lenses and teleconverters cannot be used in UV photography.

DETERMINING EXPOSURE IN VISIBLE LIGHT

With built-in TTL metering

Full-aperture exposure measurement can be performed. When used with a close-up attachment such as a PN ring or bellows, see the table at right. When the lens is mounted in the reverse position, the stop down method should be used.

Camera	Close-up attachment	Exposure measurement				
AI	PN-11	full-aperture				
	PN-1*	stop-down				
	Bellows/E2 and K rings/ close-up lenses	stop-down				
	PN-11	stop-down				
	PN-1	full-aperture				
Non-AI	Bellows/E2 and K rings/ close-up lenses	stop-down				

^{*} Some AI camera bodies with fixed meter coupling lever will not accept the PN-1 ring.

Without TTL metering

At close range, the amount of light reaching the film decreases as the lens-to-film distance increases. When non-TTL measurement is used in such a case, make exposure compensation to prevent underexposure. The table at right gives exposure factors (compensation values) with corresponding exposure increases in f/stops for non-TTL exposure measurement at reproduction ratios of 1:10 or greater.

When you want to limit the aperture compensation to one full f/stop or less, use slower shutter speeds. For example, for a 1:1.2 reproduction ratio, use a shutter speed one step slower and open the lens by 3/4 stop, or use a shutter speed two steps slower stop the lens down by 1/4 stop.

Reproduction ratio	Exposure factor	Exposure increase in f/stop
1:10	1.2	approx. 1/4
1:8	1.3	approx. 1/3
1:6	1.3	approx. 1/3
1:4	1.5	approx. 2/3
1:2	2.2	approx. 11/4
1:1.8*	2.3	approx. 11/3
1:1.6*	2.5	approx. 11/3
1:1.4*	2.8	approx. 11/2
1:1.2*	3.2	approx. 1¾
1:1*	3.8	approx. 2

^{*} with PN-11 ring

INFRARED PHOTOGRAPHY—

In infrared photography, it is necessary to make the following adjustment to the focused distance.

- 1. Focus subject.
- Reset the focusing ring to align the focused distance with the infrared focusing index.
- Attach the appropriate optional filter, such as R60, etc., and take the shot.



RECOMMENDED FOCUSING SCREENS-

Various interchangeable focusing screens are available for F3- and F2-series cameras to suit any type of lens or picture-taking situation. Those which are recommended for use with your lens are listed below. For screens used with Nikon cameras other than F3- and F2-series cameras (e.g., Nikon FA, FE2, FM2 and FE), refer to the column for F3-series cameras. For the K2, B2 and E2 focusing screens, refer to the columns on the K, B and E screens, respectively. For details, also refer to the specific focusing screen's instruction sheet.

Screen Canera	A/L	В	С	D	E	GI	G2	G3	G4	н	H2	НЗ	H4	J	K/P	М	R	т	U
F3	0	0		0	0			0	0			0	0	0	0		0	0	0
F2	0	0	3	0	0			0	0			0	0	0	0		0		

• When the Teleconverter TC-14B or TC-14 is attached to this lens, use the following table*:

Screen Canera	A/L	В	С	D	E	G1	G2	G3	G4	н	H2	НЗ	H4	J	K/P	М	R	Т	U
F3	•	0		0	0									0			۰	٠	٠
F2	٠	0		0	0									0	•		•		

• When the Teleconverter TC-301 or TC-300 is attached to this lens, use the following table*:

Screen Canera	A/L	в	С	D	E	G1	G2	G3	G4	н	H2	НЗ	H4	J	K/P	М	R	Т	U
F3	•	0		0	0			0	0					0	•		•	•	•
F2	•	0		0	0			0	0					0	٠		•		

* Teleconverter cannot be used in UV photography.

- = Excellent focusing
- = Acceptable focusing

The image is brilliant from edge to edge, but the center area (range-finder, micro-prism or cross-hair) is dim. Focus on the surrounding matte area.

- = Acceptable focusing Slight vignetting (or moire phenomenon, in the case of the microprism) affects the screen image. The image on the film, however, shows no trace of this.
- = Exposure measurement not possible Lens/screen combination permits only focusing operation.

Blank means inapplicable.

LENS CARE-

- · Although you should always keep the lens surfaces clean, rough cleaning must be avoided. Wipe with a soft, clean cotton cloth moistened with alcohol to remove grease or fingerprints from the lens surfaces.
- Keep the lens cap in place whenever the lens is not in use.
- · Attach both the front and rear caps when the lens is stored separately.
- To ensure proper fit of the lens when stored in the leather lens case, set the lens' focusing ring to the infinity (∞) setting.

SPECIFICATIONS

Focal length: 105mm Maximum aperture: f/4.5

Lens construction: 6 elements in 6 groups

Picture angle:

Weight:

23°20' Distance scale: Graduated in meters and feet from 0.48m (1.57 ft.)

to infinity (∞)

Aperture scale: f/4.5 to f/32 on both stan-

dard and aperture-directreadout scales

Reproduction ratio: Scale provided: 1:10 to 1:2 Diaphragm: Fully automatic

Via full-aperture method; Exposure measurement: meter coupling ridge pro-

> vided for AI cameras and meter coupling shoe for

non AI cameras Nikon bayonet

Mount: 52mm (P = 0.75mm)Attachment size: Dimensions:

Approx. 68.5mm dia. x 108mm when extended

from lens mounting flange; approx. 116.5mm long

(overall)

Approx. 515g

Accessories

52mm snap-on front lens cap Rear lens cap LF-1 Gelatine filter holder AF-1


Filter holder ring UR-2 52mm-square UV transmitting filter

52mm dia, screw-in filters Hard lens case CL-15S

Flexible lens pouch No. 63 Plastic lens case CP-9

Teleconverter TC-14B* Teleconverter TC-301*

* Cannot be used in UV photography.



被写界深度表 DEPTH-OF-FIELD TABLES—

撮影距離 Focused		被写界深度 Depth of field											
distance	f/4.5	f/5.6	f/8	f/11	f/16	f/22	f/32	ratio					
0.48	0.479-0.481	0.479-0.481	0.479-0.481	0.479-0.481	0.478-0.482	0.478-0.482	0.477-0.484	1/1.98					
0.50	0.499-0.501	0.499-0.501	0.499-0.501	0.498-0.502	0.498-0.502	0.497-0.503	0.496-0.505	1/2.23					
0.55	0.549-0.551	0.549-0.551	0.548-0.552	0.548-0.553	0.546-0.554	0.545-0.555	0.543-0.557	1/2.8					
0.6	0.598-0.602	0.598-0.602	0.597-0.603	0.596-0.604	0.595-0.605	0.593-0.607	0.590-0.611	1/3.33					
0.7	0.697-0.703	0.697-0.703	0.695-0.705	0.694-0.706	0.691-0.709	0.688-0.713	0.682-0.719	1/4.35					
0.8	0.796-0.804	0.795-0.805	0.793-0.807	0.790-0.810	0.786-0.814	0.781-0.820	0.773-0.830	1/5.34					
1	0.992-1.01	0.991-1.01	0.987-1.01	0.982-1.02	0.974-1.03	0.965-1.04	0.950-1.06	1/7.3					
1.2	1.19-1.21	1.19-1.22	1.18-1.22	1.17-1.23	1.16-1.25	1.14-1.26	1.12-1.29	1/9.2					
1.5	1.48-1.52	1.47-1.53	1.46-1.54	1.45-1.55	1.43-1.58	1.40-1.61	1.37-1.67	1/12.1					
2	1.96-2.04	1.95-2.05	1.93-2.08	1.90-2.11	1.86-2.16	1.82-2.23	1.75-2.35	1/16.9					
3	2.90-3.11	2.88-3.13	2.83-3.20	2.77-3.28	2.68-3.42	2.57-3.61	2.42-3.99	1/26.4					
7	6.42-7.70	6.31-7.87	6.05-8.31	5.76-8.95	5.34-10.25	4.91-12.46	4.33-19.52	1/64.5					
00	72.5-00	59.5	41.700	30.4-00	21.0-∞	15.3-∞	10.6-∞	1/00					

(ft.)

Focused				Depth of field				Reproduction
distance	1/4.5	f/5.6	f/8	f/11	f/16	f/22	f/32	ratio
(1.57) 1.6	1'6-13/16"- 1'6-13/16"	1'6-13/16''- 1'6-13/16''	1'6-3/4''- 1'6-13/16''	1'6-3/4''- 1'6-7/8''	1'6-3/4''- 1'6-7/8''	1'6-11/16''- 1'6-7/8''	1'6-11/16''- 1'6-15/16''	1/2.0
1.7	1'8-15/16''- 1'9''	1'8-15/16''- 1'9''	1'8-15/16" 1'9-1/16"	1'8-7/8''- 1'9-1/16''	1'8-7/8''- 1'9-1/8''	1'8-13/16''- 1'9-1/8''	1.8-3/4"- 1.9-1/4"	1/2.6
2.0	1'11-7/8"- 2'1/16"	1:11-7/8"- 2:1/16"	1·11-7/8··- 2·1/16··	1°11-13/16''- 2°1/8''	1'11-3/4"- 2'3/16"	1'11-11/16''- 2'1/4''	1'11-9/16''- 2'7/16''	1/3.4
2.5	2'5-13/16"- 2'6-1/8"	2'5-13/16"- 2'6-1/8"	2'5-3/4"- 2'6-3/16"	2'5-5/8''- 2'6-5/16''	2·5-1/2··- 2·6-7/16··	2·5·5/16·'- 2·6·5/8·'	2·5·1/16"- 2·6·15/16"	1/5.0
3.0	2'11-3/4"- 3'3/16"	2°11+11/16"- 3°1/4"	2'11-9/16"- 3'3/8"	2°11-7/16°'- 3°9/16°'	2°11-3/16''- 3°13/16''	2'10-7/8''- 3'1-1/8''	2'10-7/16"- 3'1-11/16"	1/6.5
4.0	3'11-7/16"- 4'1/2"	3'11-3/8''- 4'5/8''	3'11-1/8''- 4'7/8''	3'10-13/16''- 4'1-1/4''	3'10-1/4"- 4'1-13/16"-	3'9-11/16''- 4'2-9/16''	3'8-3/4"- 4'3-7/8"	1/9.4
5.0	4'11-1/8"- 5'7/8"	4'10-15/16"- 5'1-1/16"	4'10-1/2' - 5'1-9/16''	4'9-15/16''- 5'2-3/16''	4'9-1/16"- 5'3-1/4"	4'8-1/16''- 5'4-9/16''	4'6-1/2''- 5'6-15/16''	1/12.3
7.0	6'10-1/16''- 7'1-15/16''	6'9-11/16''- 7'2-3/8''	6'8-3/4''- 7'3-1/2''	6'7-5/8"- 7'4-15/16"	6'5-13/16''- 7'7-3/8''	6'3-11/16''- 7'10-9/16''	6'9/16''- 8'4-3/8''	1/18.2
10.0	9'7-7/8''- 10'4''	9'7''-10'5''	9'5"-10'7"	9°2-5/8"- 10°11"	8'10-13/16"- 11'5"	8'6-11/16"- 12'1"	8'1/2"- 13'4"	1/26.9
20.0	18'6"-21'8"	18'3"-22'1"	17'7"-23'1"	16'10''-24'7''	15'9"-27'6"	14'7"-32'1"	13'-44'8"	1/55.9
00	238'-∞	195'	136′-∞	99'	68'-00	50'	34'-00	1/00

		正方向 in normal posi	tion		ズ逆向き is in reverse posi	tion
使用器具 Close-up attachment	機影倍率 Reproduction ratio	被写界面積 Subject field	機影距離 Focused distance	撮影信本 Reproduction ratio	被写界面積 Subject field	推影距離 Focused distance
クローズアップレンズNo.0 Close-Up Lens No. 0	1/14-1/1.7	32.8 × 49.2- 4.0 × 6.1	159-43.9		-	-
クローズアップレンズNo.1 Close-Up Lens No. 1	1/6.5-1/1.4	15.5 × 23.2- 3.5 × 5.2	84.5-40.9	121	-	Ψ.
クローズアップレンズNo.2 Close-Up Lens No. 2	1/3.2-1/1.1	7.8 × 11.6 – 2.7 × 4.0	50.4-36.6		-	-
クローズアップレンズNo.3T Close-Up Lens No. 3T	1/6.4-1/1.4	15.3 × 22.9- 3.4 × 5.1	82.9-40.5	_ E	149	_
クローズアップレンズNo.4T Close-Up Lens No. 4T	1/3.3-1/1.1	7.8 × 11.7- 2.7 × 4.0	50.1-36.3	-		
EZリング E2 Ring	1/7.5-1/1.6	18.0 × 27.1 – 3.8 × 5.7	102.3-45.1	-		-
Kリング K Ring Set	1/18.1-1/1.1	43.5 × 65.3- 2.5 × 3.8	213.2-42.9	-	2.00	
PKリング PK-Series Rings	1/13.2-1.0	31.6 × 47.3 – 2.5 × 3.7	161.0-42.9	-	1-1	-
PNリング PN Ring	1/2.0-1.0	4.8 × 7.2- 2.4 × 3.6	48.1-42.9	-	-	7
ベローズアタッチメントPB-4, PB-5 Bellows Focusing Attachment PB-4, PB-5	1/2.4-1.8	5.9 × 8.8- 1.4 × 2.0	51.9-46.3	1/3.5-1.6	8.3 × 12.5 – 1.5 × 2.2	61.4-45.5
ベローズアタッチメントPB-6 Bellows Focusing Attachment PB-6	1/2.2-2.0	5.3 × 7.9- 1.2 × 1.8	49.7-48.0	1/5.3-1/1.3	12.6 × 18.9 – 3.1 × 4.6	79.2-43.5
エクステンションペローズPB-6E Extension Bellows PB-6E	1/2.2-4.2	5.3 × 7.9 – 0.58 × 0.86	49.7-68.2	1/5.3-3.0	12.6 × 18.9- 0.81 × 1.2	79.2-56.6
複写装置PF-2, PF-3, PF-4 Reprocopy Outfit PF-2, PF-3, PF-4	1/5.9-1/2	14.1 × 21.1- 4.8 × 7.2	85.3-48.0		- 1	-

- ■Kリングのはじめの数値はKリング I 個使用のとき、あとの数値はKI-K5リングを連結したときのものです。
- **PKリングのほじめの数値はPK-IリングまたはPK-IリングI 保使用のとき、あとの数値はPK-I-PK-3またはPK-II-PK-I3リングを連結したときのも のです。
- ● 権写装置PF-2、PF-3、PF-4はレンズ単体で使用したとき、権写台の動物面上の機影可能範囲を示します。
- The first values are for the K1 ring used alone and the second ones for all five rings together.
 The first values are for the PK-1 or PK-11 ring used alone and the second ones for three (PK-1-PK-3 or PK-11-PK-13) used together.
 The figures shown here represent the ranges obtained with the subject on the baseplate, using the lens without any close-up attachment.

(in.)

Т		Lens	s in normal position	n	Lens	in reverse positio	n
	Close-up attachment	Reproduction ratio	Subject field	Focused distance	Reproduction ratio	Subject field	Focused distance
İ	Close-Up Lens No. 0	1/14-1/1.7	12.9 × 19.4— 1.6 × 2.4	62.6-17.3	-		7
İ	Close-Up Lens No. 1	1/6.5-1/1.4	6.1 × 9.1- 1.4 × 2.0	33.3-16.1	12	-	- 4
İ	Close-Up Lens No. 2	1/3.2-1/1.1	3.1 × 4.6- 1.1 × 1.6	19.8-14.4	-	-	-
İ	Close-Up Lens No. 3T	1/6.4-1/1.4	6.0 × 9.0- 1.3 × 2.0	32.6-15.9	-	-	-
	Close-Up Lens No. 4T	1/3.3-1/1.1	3.1 × 4.6- 1.1 × 1.6	19.7-14.3	-	-	- 5
Ì	E2 Ring	1/7.5-1/1.6	7.1 × 10.7- 1.5 × 2.2	40.3-17.8	-	2	27
Ì	K Ring Set	1/18.1-1/1.1	17.1 × 25.7- 1.0 × 1.5	83.9-16.9	-		-
1	PK-Series Ring	1/13.2-1.0	12.4 × 18.6- 1.0 × 1.5	63.4-16.9	-	-	
Ì	PN Ring	1/2.0-1.0	1.9 × 2.8- 0.9 × 1.4	18.9-16.9	-	-	1,500
Ì	Bellows Focusing Attachment PB-4, PB-5	1/2.4-1.8	2.3 × 3.5 – 0.54 × .081	20.4-18.2	1/3.5-1.6	3.3 × 4.9 – 0.58 × 0.87	24.2-17.5
Ì	Bellows Focusing Attachment PB-6	1/2.2-2.0	2.1 × 3.1- 0.48 × 0.72	19.6-18.9	1/5.3-1/1.3	5.0 × 7.5 – 1.2 × 1.8	31.2-17.
Ì	Extension Bellows PB-6E	1/2.2-4.2	2.1 × 3.1- 0.23 × 0.34	19.6-26.8	1/5.3-3.0	5.0 x 7.5- 0.32 x 0.48	31.2-22.
1	Reprocopy Outfit PF-2, PF-3, PF-4	1/5.9-1/2	5.6 × 8.3- 1.9 × 2.8	33.6-18.9	-	-	-

The first values are for the K1 ring used alone and the second ones for all five rings together.
 The first values are for the PK-1 or PK-11 ring used alone and the second ones for three (PK1-PK-3 or PK-11-PK-13) used together.
 The figures shown here represent the ranges obtained with the subject on the baseplate, using the lens without any close-up attachment.

..

...

